

wrightway2MT INDUSTRIAL BIN TIPPER TO EMPTY 660 OR 1100 LITRE 4-WHEELED SKIP BINS:

1: LOCATED & SECURED

Ensure machine is safely located against skip with wind-down rear brakes and braked castors fully engaged and the cradle is at ground level.



2: ACTIVATE

Insert key, turn key ON.

NOTE: The doors will not open and the machine will not operate unless the cradle is fully located at ground level and the electronic sensors aligned.

3: OPEN DOORS

Push and hold DOOR button while partially opening the doors by the door handles (See Right).

Release DOOR button, and open doors fully to allow access to the cradle (see Right).



4: LOAD CRADLE

Wheel the bin forward onto cradle.

Ensure all the bin is located as far forward as possible.



5: CLOSE DOORS

CLOSE DOORS


The machine will not operate if the doors are not fully closed.

6: OPERATE

Press and hold UP button until the bin is fully inverted.

Release UP Button.

Press and hold DOWN button until cradle is at ground level (cradle lowers by gravity).



7: REMOVE BIN

Push and hold DOOR button while opening the doors by the door handles.

Remove bin and close the doors.

8: REPEAT OR COMPLETE CYCLE

Repeat operation to empty subsequent bins.

If machine is not to be used immediately, close doors, turn key to OFF, remove key and return the key to a secured location.

NOTE: Battery operated machines MUST be re-charged overnight if used on a daily basis.